

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

TABLE OF CONTENTS

CHAPTER He-P 4000 NEW HAMPSHIRE RULES FOR THE CONTROL OF RADIATION

PART He-P 4001 SCOPE, EXEMPTIONS, AND GENERAL PROVISIONS

- Section He-P 4001.01 Scope
- Section He-P 4001.02 Exemptions
- Section He-P 4001.03 Records
- Section He-P 4001.04 Inspections
- Section He-P 4001.05 Tests
- Section He-P 4001.06 Prohibited Uses
- Section He-P 4001.07 Deliberate Misconduct
- Section He-P 4001.08 Communications
- Section He-P 4001.09 Units of Exposure and Dose
- Section He-P 4001.10 Units of Activity
- Section He-P 4001.11 Determination of Year

PART He-P 4002 - RESERVED

PART He-P 4003 DEFINITIONS

- Section He-P 4003.01 Definitions

PART He-P 4004 - 4018 - RESERVED

PART He-P 4019 NOTICES, INSTRUCTIONS, AND REPORTS TO WORKERS; INSPECTIONS

- Section He-P 4019.01 Purpose
- Section He-P 4019.02 Scope
- Section He-P 4019.03 Posting of Notices to Workers
- Section He-P 4019.04 Instructions to Workers
- Section He-P 4019.05 Notifications and Reports to Individuals
- Section He-P 4019.06 Presence of Representatives of Licensees or Registrants and Workers
During Inspections
- Section He-P 4019.07 Consultation with Workers During Inspections
- Section He-P 4019.08 Requests by Workers for Inspections
- Section He-P 4019.09 Inspections not Warranted; Informal Review

PART He-P 4020 STANDARDS FOR PROTECTION AGAINST RADIATION

- Section He-P 4020.01 Purpose
- Section He-P 4020.02 Scope
- Section He-P 4020.03 Implementation
- Section He-P 4020.04 Radiation Protection Programs
- Section He-P 4020.05 Occupational Dose Limits for Adults
- Section He-P 4020.06 Compliance with Requirements for Summation of External and Internal
Doses
- Section He-P 4020.07 Determination of External Dose from Airborne Radioactive Material
- Section He-P 4020.08 Determination of Internal Exposure
- Section He-P 4020.09 Determination of Prior Occupational Dose
- Section He-P 4020.10 Planned Special Exposures
- Section He-P 4020.11 Occupational Dose Limits for Minors
- Section He-P 4020.12 Dose to an Embryo/Fetus

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

- Section He-P 4020.13 Dose Limits for Individual Members of the Public
- Section He-P 4020.14 Compliance with Dose Limits for Individual Members of the Public

PART He-P 4021 RECORDS, REPORTS, AND ADDITIONAL REQUIREMENTS

- Section He-P 4021.01 Units and Quantities for Records
- Section He-P 4021.02 Records of Radiation Protection Programs
- Section He-P 4021.03 Records of Surveys
- Section He-P 4021.04 Records of Tests for Leakage or Contamination of Sealed Sources
- Section He-P 4021.05 Records of Prior Occupational Dose
- Section He-P 4021.06 Records of Planned Special Exposures
- Section He-P 4021.07 Records of Individual Monitoring Results
- Section He-P 4021.08 Records of Dose to Individual Members of the Public
- Section He-P 4021.09 Records of Waste Disposal
- Section He-P 4021.10 Records of Testing Entry Control Devices for Very High Radiation Areas:
Irradiators
- Section He-P 4021.11 Form of Records
- Section He-P 4021.12 Reports of Stolen, Lost, or Missing Licensed or Registered Sources of
Radiation
- Section He-P 4021.13 Notification of Incidents
- Section He-P 4021.14 Reports of Exposures, Radiation Levels, and Concentrations of
Radioactive Material Exceeding the Limits
- Section He-P 4021.15 Reports of Planned Special Exposures
- Section He-P 4021.16 Report to Individuals of Exceeding Dose Limits
- Section He-P 4021.17 Reports of Individual Monitoring
- Section He-P 4021.18 Notifications and Reports to Individuals
- Section He-P 4021.19 Reports of Leaking or Contaminated Sealed Sources
- Section He-P 4021.20 Additional Requirements
- Section He-P 4021.21 Permissible Levels of Surface Contamination
- Section He-P 4021.22 Reports of Transactions Involving Nationally Tracked Sources

PART He-P 4022 SURVEYS AND MONITORING

- Section He-P 4022.01 General
- Section He-P 4022.02 Conditions Requiring Individual Monitoring of External and Internal
Occupational Dose
- Section He-P 4022.03 Location of Individual Monitoring Devices
- Section He-P 4022.04 Control of Access to High Radiation Areas
- Section He-P 4022.05 Control of Access to Very High Radiation Areas
- Section He-P 4022.06 Control of Access to Very High Radiation Areas; Irradiators
- Section He-P 4022.07 Control of Radioactive Material in the Air
- Section He-P 4022.08 Use of Individual Respiratory Protection Equipment
- Section He-P 4022.09 Security of Stored Sources of Radiation
- Section He-P 4022.10 Control of Sources of Radiation not in Storage
- Section He-P 4022.11 Caution Signs
- Section He-P 4022.12 Posting Requirements
- Section He-P 4022.13 Exceptions to Posting Requirements
- Section He-P 4022.14 Labeling Containers and Radiation Machines
- Section He-P 4022.15 Exemptions to Labeling Requirements
- Section He-P 4022.16 Procedures for Receiving and Opening Packages

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

PART He-P 4023 WASTE DISPOSAL

- Section He-P 4023.01 Disposal Requirements
- Section He-P 4023.02 Method for Obtaining Approval of Proposed Disposal Procedures
- Section He-P 4023.03 Disposal by Release into Sanitary Sewerage
- Section He-P 4023.04 Treatment or Disposal by Incineration
- Section He-P 4023.05 Disposal of Specific Wastes
- Section He-P 4023.06 Transfer for Disposal and Manifests
- Section He-P 4023.07 Compliance with Environmental and Health Protection Regulations
- Section He-P 4023.08 disposal of Certain Byproduct Material

PART He-P 4024 DECOMMISSIONING

- Section He-P 4024.01 Purpose
- Section He-P 4024.02 Scope
- Section He-P 4024.03 Exemptions
- Section He-P 4024.04 Minimization of Contamination
- Section He-P 4024.05 Continuation of Licenses Beyond Expiration Date
- Section He-P 4024.06 Decommissioning Timeliness
- Section He-P 4024.07 Decommissioning Plan
- Section He-P 4024.08 Completion of Decommissioning
- Section He-P 4024.09 Termination of a License Without Restriction
- Section He-P 4024.10 License Termination Under Restricted Conditions
- Section He-P 4024.11 Alternate Criteria for License Termination
- Section He-P 4024.12 Requirement to Use Peak Annual TEDE
- Section He-P 4024.13 Public Notification and Public Participation
- Section He-P 4024.14 Applicability of Decommissioning Criteria Following License Termination

PART He-P 4030 LICENSING OF RADIOACTIVE MATERIAL

- Section He-P 4030.01 Requirements
- Section He-P 4030.02 Exemptions, Source Material
- Section He-P 4030.03 Exemptions, Radioactive Materials Other Than Source Materials
- Section He-P 4030.04 Exemptions, U.S. Government Contractors
- Section He-P 4030.05 Radioactive Drug: Capsules Containing Carbon-14 Urea for "In Vivo" Diagnostic Use for Humans
- Section He-P 4030.06 Types of Licenses
- Section He-P 4030.07 Specific Licenses, Filing or Application
- Section He-P 4030.08 Quantities of Radioactive Materials Requiring Consideration of the Need for an Emergency Plan for Responding to a Release
- Section He-P 4030.09 Specific Licenses, Requirements for Issuance
- Section He-P 4030.10 Specific Licenses, Issuance
- Section He-P 4030.11 Specific Licenses, Expiration
- Section He-P 4030.12 Specific Licenses, Renewal
- Section He-P 4030.13 Specific Licenses, Amendment at Request of Licensee
- Section He-P 4030.14 Specific Licenses, DHHS/BRH Action of Applications to Renew or Amend
- Section He-P 4030.15 Specific Licenses, Inalienability
- Section He-P 4030.16 Specific Licenses, Transfer of Material
- Section He-P 4030.17 Specific Licenses, Modification, Revocation, and Termination
- Section He-P 4030.18 Reciprocal Recognition of Specific Licenses

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

PART He-P 4031 GENERAL LICENSES

- Section He-P 4031.01 Purpose and Scope
- Section He-P 4031.02 Terms and Conditions
- Section He-P 4031.03 General Licenses - Source Material
- Section He-P 4031.04 General Licenses – Byproduct Material Other Than Source Material
- Section He-P 4031.05 General License to Install Devices Generally Licensed in He-P 4031.04(b)

PART He-P 4032 SPECIFIC LICENSES FOR MANUFACTURE OR TRANSFER OF CERTAIN ITEMS CONTAINING RADIOACTIVE MATERIAL

- Section He-P 4032.01 Purpose
- Section He-P 4032.02 Scope
- Section He-P 4032.03 Licensing the Manufacture and Distribution of Devices to Persons Generally Licensed
- Section He-P 4032.04 Licensing the Introduction of Radioactive Material Into Products in Exempt Concentrations
- Section He-P 4032.05 Manufacture and Distribution of Radiopharmaceuticals Containing Radioactive Material for Medical Use Under Group Licenses
- Section He-P 4032.06 Manufacture and Distribution of Generators or Reagent Kits for Preparation of Radiopharmaceuticals Containing Radioactive Material
- Section He-P 4032.07 Manufacture and Distribution of Sources or Devices Containing Radioactive Material for Medical Use
- Section He-P 4032.08 Special Requirements for the Manufacture, Assembly, or Repair of Luminous Safety Devices for Use in Aircraft
- Section He-P 4032.09 Licensing the Distribution of Radioactive Material in Exempt Quantities
- Section He-P 4032.10 Licensing the Incorporation of Radioactive Material Other Than Source or Byproduct Material into Gas and Aerosol Detectors
- Section He-P 4032.11 Special Requirements for License to Manufacture, Import or Initially Distribute Sealed Sources or Devices Containing Sealed Sources to Persons Having a Specific License
- Section He-P 4032.12 Prohibition

PART He-P 4033 SPECIFIC LICENSES OF BROAD SCOPE FOR OTHER THAN HUMAN USE

- Section He-P 4033.01 Purpose
- Section He-P 4033.02 Scope
- Section He-P 4033.03 Types of Specific Licenses of Broad Scope
- Section He-P 4033.04 Application for Specific Licenses of Broad Scope
- Section He-P 4033.05 Requirements for the Issuance of Specific Licenses of Broad Scope
- Section He-P 4033.06 Conditions of Specific Licenses of Broad Scope
- Section He-P 4033.07 License Quantities for Licenses of Broad Scope

PART He-P 4034 RADIATION SAFETY REQUIREMENTS FOR INDUSTRIAL RADIOGRAPHIC OPERATIONS

- Section He-P 4034.01 Purpose
- Section He-P 4034.02 Scope
- Section He-P 4034.03 Definitions
- Section He-P 4034.04 Exemptions
- Section He-P 4034.05 Licensing and Registration Requirements for Industrial Radiography Operations
- Section He-P 4034.06 Performance Requirements for Industrial Radiography Equipment

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

- Section He-P 4034.07 Limits on External Radiation Levels From Storage Containers and Source Changers
- Section He-P 4034.08 Locking of Radiographic Exposure Devices, Storage Containers and Source Changers
- Section He-P 4034.09 Radiation Survey Instruments
- Section He-P 4034.10 Leak Testing and Replacement of Sealed Sources
- Section He-P 4034.11 Quarterly Inventory
- Section He-P 4034.12 Inspection and Maintenance of Radiation Machines, Radiographic Exposure Devices, Transport and Storage Containers, Associated Equipment, Source Changers, and Survey Instruments
- Section He-P 4034.13 Permanent Radiographic Installations
- Section He-P 4034.14 Labeling, Storage, and Transportation
- Section He-P 4034.15 Conducting Industrial Radiographic Operations
- Section He-P 4034.16 Radiation Safety Officer
- Section He-P 4034.17 Training
- Section He-P 4034.18 Operating and Emergency Procedures
- Section He-P 4034.19 Supervision of Radiographers' Assistants
- Section He-P 4034.20 Personnel Monitoring
- Section He-P 4034.21 Radiation Surveys
- Section He-P 4034.22 Surveillance
- Section He-P 4034.23 Posting
- Section He-P 4034.24 Records for Industrial Radiography
- Section He-P 4034.25 Records of Receipt and Transfer of Sources of Radiation
- Section He-P 4034.26 Records of Radiation Survey Instruments
- Section He-P 4034.27 Records of Leak Testing of Sealed Sources and Devices Containing DU
- Section He-P 4034.28 Records of Quarterly Inventory
- Section He-P 4034.29 Utilization Logs
- Section He-P 4034.30 Records of Inspection and Maintenance of Radiation Machines, Radiographic Exposure Devices, Transport and Storage Containers, Associated Equipment, Source Changers, and Survey Instruments
- Section He-P 4034.31 Records of Alarm System and Entrance Control Checks at Permanent Radiographic Installations
- Section He-P 4034.32 Records of Training and Certification
- Section He-P 4034.33 Copies of Operating and Emergency Procedures
- Section He-P 4034.34 Records of Personnel Monitoring
- Section He-P 4034.35 Records of Radiation Surveys
- Section He-P 4034.36 Form of Records
- Section He-P 4034.37 Location of Documents and Records
- Section He-P 4034.38 Notifications
- Section He-P 4034.39 Specific Requirements for Radiographic Personnel Performing Industrial Radiography

PART He-P 4035 USE OF RADIONUCLIDES IN THE HEALING ARTS

- Section He-P 4035.01 Purpose
- Section He-P 4035.02 Scope
- Section He-P 4035.03 Definitions
- Section He-P 4035.04 License Required
- Section He-P 4035.05 License Amendments
- Section He-P 4035.06 Notifications
- Section He-P 4035.07 ALARA Program

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

- Section He-P 4035.08 Radiation Safety Officer
- Section He-P 4035.09 Radiation Safety Committee
- Section He-P 4035.10 Statement of Authorities and Responsibilities
- Section He-P 4035.11 Supervision
- Section He-P 4035.12 Mobile Nuclear Medicine Service Administrative Requirements
- Section He-P 4035.13 Quality Management Program
- Section He-P 4035.14 Records, Notifications, and Reports of Misadministrations
- Section He-P 4035.15 Suppliers
- Section He-P 4035.16 Quality Control of Diagnostic Equipment
- Section He-P 4035.17 Possession, Use, Calibration, and Check of Dose Calibrators
- Section He-P 4035.18 Calibration and Check of Survey Instruments
- Section He-P 4035.19 Assay of Radiopharmaceutical Dosages
- Section He-P 4035.20 Authorization for Calibration and Reference Sources
- Section He-P 4035.21 Requirements for Possession of Sealed Sources and Brachytherapy Sources
- Section He-P 4035.22 Syringe Shields and Labels
- Section He-P 4035.23 Vial Shields and Labels
- Section He-P 4035.24 Surveys for Ambient Radiation Dose Rate and Contamination
- Section He-P 4035.25 Release of Patients or Human Research Subjects Containing Radiopharmaceuticals or Permanent Implants
- Section He-P 4035.26 Mobile Nuclear Medicine Service Technical Requirements
- Section He-P 4035.27 Storage of Volatiles and Gases
- Section He-P 4035.28 Decay-In-Storage
- Section He-P 4035.29 Use of Radiopharmaceuticals for Uptake, Dilution, or Excretion Studies
- Section He-P 4035.30 Possession of Survey Instrument for Use of Radiopharmaceuticals for Uptake, Dilution or Excretion Studies
- Section He-P 4035.31 Use of Radiopharmaceuticals, Generators, and Reagent Kits for Imaging and Localization Studies
- Section He-P 4035.32 Radionuclide Contaminants
- Section He-P 4035.33 Control of Aerosols and Gases
- Section He-P 4035.34 Possession of Survey Instruments for Use of Radiopharmaceuticals, Generators, and Reagent Kits for Imaging and Localization Studies
- Section He-P 4035.35 Use of Radiopharmaceuticals for Therapy
- Section He-P 4035.36 Safety Instruction for Use of Radiopharmaceuticals for Therapy
- Section He-P 4035.37 Safety Precautions for Use of Radiopharmaceuticals for Therapy
- Section He-P 4035.38 Possession of Survey Instruments for Use of Radiopharmaceuticals for Therapy
- Section He-P 4035.39 Use of Sealed Sources for Diagnosis
- Section He-P 4035.40 Availability of Survey Instruments for Use of Sealed Sources for Diagnosis
- Section He-P 4035.41 Use of Sources for Brachytherapy
- Section He-P 4035.42 Safety Instruction for Use of Brachytherapy
- Section He-P 4035.43 Safety Precautions for Use of Brachytherapy Sources
- Section He-P 4035.44 Brachytherapy Sources Inventory
- Section He-P 4035.45 Release of Patients or Human Research Subjects Treated With Temporary Implants
- Section He-P 4035.46 Possession of Survey Instruments for Use of Brachytherapy Sources
- Section He-P 4035.47 Use of a Sealed Source in a Teletherapy Unit
- Section He-P 4035.48 Maintenance and Repair Restrictions for Sealed Source Teletherapy
- Section He-P 4035.49 Amendments for Use of a Sealed Source in Teletherapy
- Section He-P 4035.50 Safety Instruction for Sealed Source Teletherapy

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

- Section He-P 4035.51 Safety Precautions for Sealed Source Teletherapy
- Section He-P 4035.52 Possession of Survey Instrument for Use of Sealed Source Teletherapy
- Section He-P 4035.53 Dosimetry Equipment for Sealed Source Teletherapy
- Section He-P 4035.54 Full Calibration Measurements for Use of Sealed Source Teletherapy
- Section He-P 4035.55 Periodic Spot-Checks for Use of Sealed Source Teletherapy
- Section He-P 4035.56 Radiation Surveys for Teletherapy Facilities
- Section He-P 4035.57 Safety Spot-Checks for Teletherapy Facilities
- Section He-P 4035.58 Modification of Teletherapy Unit or Room Before Beginning a Treatment Program
- Section He-P 4035.59 Reports of Teletherapy Surveys, Checks, Tests and Measurements
- Section He-P 4035.60 Five Year Inspection of Teletherapy Units
- Section He-P 4035.61 Radiation Safety Officer Training
- Section He-P 4035.62 Training for Experienced Radiation Safety Officer
- Section He-P 4035.63 Training for Uptake, Dilution, or Excretion Studies
- Section He-P 4035.64 Training for Imaging and Localization Studies
- Section He-P 4035.65 Training for Therapeutic Use of Radiopharmaceuticals
- Section He-P 4035.66 Training for Therapeutic Use of Brachytherapy Sources
- Section He-P 4035.67 Training for Ophthalmic Use of Strontium-90
- Section He-P 4035.68 Training for Use of Sealed Sources for Diagnosis
- Section He-P 4035.69 Training for Teletherapy
- Section He-P 4035.70 Training for Teletherapy Physicist
- Section He-P 4035.71 Training for Experienced Authorized Users
- Section He-P 4035.72 Physician Training in a Three-Month Program
- Section He-P 4035.73 Recentness of Training
- Section He-P 4035.74 Training for an Authorized Nuclear Pharmacist
- Section He-P 4035.75 Training for Experienced Nuclear Pharmacist

PART He-P 4036 LICENSING AND RADIATION SAFETY REQUIREMENTS FOR IRRADIATORS

- Section He-P 4036.01 Purpose
- Section He-P 4036.02 Scope
- Section He-P 4036.03 Definitions
- Section He-P 4036.04 Incorporation of 10 CFR Part 36

PART He-P 4037 TRANSPORTATION OF RADIOACTIVE MATERIAL

- Section He-P 4037.01 Purpose
- Section He-P 4037.02 Scope
- Section He-P 4037.03 Definitions
- Section He-P 4037.04 Incorporation of 10 CFR Part 71

PART He-P 4039 RADIATION SAFETY REQUIREMENTS FOR WIRELINE SERVICES OPERATIONS AND SUBSURFACE TRACER STUDIES

- Section He-P 4039.01 Purpose
- Section He-P 4039.02 Scope
- Section He-P 4039.03 Definitions
- Section He-P 4039.04 Incorporation of 10 CFR Part 39

PART He-P 4040 REGISTRATION OF RADIATION MACHINES AND PROVIDERS OF SERVICES

- Section He-P 4040.01 Purpose
- Section He-P 4040.02 Scope

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

- Section He-P 4040.03 Shielding Plan Review
- Section He-P 4040.04 Registration of Radiation Machines
- Section He-P 4040.05 Exemptions
- Section He-P 4040.06 Application for Registration of Servicing and Services
- Section He-P 4040.07 Expiration of Certificates of Registration
- Section He-P 4040.08 Renewal of Registration
- Section He-P 4040.09 Assembler and/or Transferor Obligation
- Section He-P 4040.10 Reciprocal Recognition of Out-of-State Radiation Machines
- Section He-P 4040.11 Radiation Machines in Storage
- Section He-P 4040.12 Waivers

PART He-P 4041 USE OF RADIATION MACHINES: DEFINITIONS

- Section He-P 4041.01 Scope
- Section He-P 4041.02 Definitions

PART He-P 4042 RESERVED

PART He-P 4043 RADIATION SAFETY REQUIREMENTS FOR ANALYTICAL X-RAY EQUIPMENT

- Section He-P 4043.01 Purpose
- Section He-P 4043.02 Scope
- Section He-P 4043.03 Definitions
- Section He-P 4043.04 Equipment Requirements
- Section He-P 4043.05 Area Requirements
- Section He-P 4043.06 Operating Requirements
- Section He-P 4043.07 Personnel Requirements

PART He-P 4044 RADIATION REQUIREMENTS FOR PARTICLE ACCELERATORS

- Section He-P 4044.01 Purpose
- Section He-P 4044.02 Scope
- Section He-P 4044.03 Registration Requirements
- Section He-P 4044.04 General Requirements for the Issuance of a Registration for Particle Accelerators
- Section He-P 4044.05 Human Use of Particle Accelerators
- Section He-P 4044.06 Limitations
- Section He-P 4044.07 Shielding and Safety Design Requirements
- Section He-P 4044.08 Particle Accelerator Controls and Interlock Systems
- Section He-P 4044.09 Warning Devices
- Section He-P 4044.10 Operating Procedures
- Section He-P 4044.11 Radiation Monitoring Requirements
- Section He-P 4044.12 Ventilation Systems

PART He-P 4045 USE OF RADIATION MACHINES: ADMINISTRATIVE REQUIREMENTS

- Section He-P 4045.01 Purpose
- Section He-P 4045.02 General Requirements
- Section He-P 4045.03 Administrative Controls
- Section He-P 4045.04 Healing Arts Screening
- Section He-P 4045.05 Information and Maintenance Record and Associated Information
- Section He-P 4045.06 X-ray Utilization Log
- Section He-P 4045.07 X-ray Film Processing Facilities and Practices

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

PART He-P 4046 USE OF RADIATION MACHINES: GENERAL REQUIREMENTS FOR ALL
DIAGNOSTIC AND VETERINARY X-RAY SYSTEMS

- Section He-P 4046.01 General Requirements for All Diagnostic X-ray
- Section He-P 4046.02 Fluoroscopic X-ray Systems - Limitation of Useful Beam
- Section He-P 4046.03 Fluoroscopic X-ray Systems - Activation of the Fluoroscopic Tube
- Section He-P 4046.04 Fluoroscopic X-ray Systems - Exposure Rate Limits
- Section He-P 4046.05 Fluoroscopic X-ray Systems - Barrier Transmitted Radiation Rate Limits
- Section He-P 4046.06 Fluoroscopic X-ray Systems - Additional Requirements
- Section He-P 4046.07 Radiographic Systems Other Than Fluoroscopic, Dental Intraoral, or
Computed Tomography X-ray Systems
- Section He-P 4046.08 Certified Diagnostic Systems Only
- Section He-P 4046.09 Intraoral Dental Radiographic Systems
- Section He-P 4046.10 Computed Tomography X-ray Systems Requirements for Equipment
- Section He-P 4046.11 Computed Tomography X-ray Systems - Facility Design Requirements
- Section He-P 4046.12 Computed Tomography X-ray Systems - Surveys, Calibrations, Spot Checks,
and Operating Procedures
- Section He-P 4046.13 Mammography
- Section He-P 4046.14 Bone Densitometry

PART He-P 4047 USE OF RADIATION MACHINES: THERAPEUTIC RADIATION MACHINES

- Section He-P 4047.01 Purpose
- Section He-P 4047.02 Scope
- Section He-P 4047.03 Definitions
- Section He-P 4047.04 General Administrative Requirements for Facilities Using Therapeutic
Radiation Machines
- Section He-P 4047.05 General Technical Requirements for Facilities Using Therapeutic Radiation
Machines
- Section He-P 4047.06 Therapeutic Radiation Machines of Less Than 500 kV
- Section He-P 4047.07 Therapeutic Radiation Machines - Photon Therapy Systems (500 kV and
Above and Electron Therapy Systems (500 keV and Above)
- Section He-P 4047.08 Calibration of Survey Instruments
- Section He-P 4047.09 Shielding and Safety Design Requirements

PARTS He-P 4048 - 4061 RESERVED

PART He-P 4062 REQUIREMENTS FOR TRANSFER OF LOW-LEVEL RADIOACTIVE WASTE
FOR DISPOSAL AT LAND DISPOSAL FACILITIES, MANIFESTS, RECORDS,
REPORTS, QUALITY ASSURANCE, AND AUDITS

- Section He-P 4062.01 Purpose
- Section He-P 4062.02 Scope
- Section He-P 4062.03 Transfer for Disposal and Manifests

PART He-P 4070 FEES FOR CERTIFICATES OF REGISTRATION, RADIOACTIVE MATERIAL
LICENSES, AND OTHER REGULATORY SERVICES

- Section He-P 4070.01 Purpose
- Section He-P 4070.02 Scope
- Section He-P 4070.03 Payment of Fees
- Section He-P 4070.04 Method of Payment
- Section He-P 4070.05 Schedule of Annual Fees for Radioactive Material Licenses
- Section He-P 4070.06 Schedule of Annual Fees for Certificates of Registration for Radiation
Machines

NEW HAMPSHIRE CODE OF ADMINISTRATIVE RULES

- Section He-P 4070.07 Proration of Annual Fees for Registration of Radiation Machines
- Section He-P 4070.08 Administrative Fines
- Section He-P 4070.09 Insufficient Funds

PART He-P 4071 LOW-LEVEL RADIOACTIVE WASTE MANAGEMENT FUND

- Section He-P 4071.01 Purpose
- Section He-P 4071.02 Scope
- Section He-P 4071.03 Quarterly Reports and Fees
- Section He-P 4071.04 Record-Keeping
- Section He-P 4071.05 Exemptions

PART He-P 4072 - 4089 RESERVED

PART He-P 4090 ANNUAL LIMITS ON INTAKE (ALI) AND DERIVED AIR CONCENTRATIONS (DAC) OF RADIONUCLIDES FOR OCCUPATIONAL EXPOSURE; EFFLUENT CONCENTRATIONS; CONCENTRATIONS FOR RELEASE TO SANITARY SEWERAGE

- Section He-P 4090.01 Annual Limits on Intake (ALI) and Derived Air Concentrations (DAC) or Radionuclides For Occupational Exposure; Effluent Concentrations; Concentrations for Release To Sanitary Sewerage

PART He-P 4091 QUANTITIES FOR USE WITH DECOMMISSIONING

- Section He-P 4091.01 Quantities for Use With Decommissioning
- Section He-P 4091.02 Quantities for Use with Decommissioning for Natural Thorium and Uranium
- Section He-P 4091.03 Combination of Isotopes

PART He-P 4092 QUANTITIES¹ OF RADIOACTIVE MATERIAL REQUIRING LABELING

- Section He-P 4092.01 Quantities^{1 a/} of Radioactive Material Requiring Labeling

PART He-P 4093 EXEMPT CONCENTRATIONS

- Section He-P 4093.01 Exempt Concentrations

PART He-P 4095 ASSIGNED PROTECTION FACTORS FOR RESPIRATORS

- Section He-P 4095.01 Assigned Protection Factors for Respirators
- Section He-P 4095.02 Additional Requirements for Protection Factors for Respirators

PART He-P 4096 EXEMPT QUANTITIES

- Section He-P 4096.01 Exempt Quantities
- Section He-P 4096.02 Derivation of Combination Limits

PART He-P 4097 NATIONALLY TRACKED SOURCE THRESHOLDS

- Section He-P 4097.01 Nationally Tracked Source Thresholds
- Section He-P 4097.02 Conversion Between Units